

Applications

Industry / Customer Group	Food processing
Application	Conveyors
Country	Canada
Product	SPBS 2901
Variations	
Application	
Details	This customer sorts and grades cucumbers. The cucumbers rest in individual trays as they travel down the length of the conveyor. If a cucumber is positioned incorrectly it will cause the tray to break when it reaches the end of the processing line. The customer mounted a SpacePak SPBS 2901 5 to detect product above the height of the trays and stop the line. Before installing the SpacePak sensor the customer was experiencing 2-4 broken trays per week. Each broken tray causes the line to be down for up to 1.5 hours, stopping work for 64 workers and costing thousands of dollars in downtime. Since installation of the SpacePak sensor there have been no tray breakages.
Reference:	TELCO 1803221090

COPYRIGHT® NOTICE

All images are the property of Telco. Telco does not permit any unauthorised use or reproduction without prior written consent. All rights reserved.