

Applications

Industry / Customer Group	Material Handling / Packaging / Processing
Application	Detection of lettuce heads on a conveyor
Country	USA
Product	LT/LR
Variations	

Application



Details

The LT/LR sensors are mounted along the side of a conveyor belt transporting lettuce heads. Heavy water spray on the lettuces caused the previous sensors to fail and the lettuce leaves that came off during transport on the conveyor frequently blocked the sensors causing down time. With Telco this does not happen and they continue working despite the water and the leaves that block the sensors.

Reference: TELCO 0903061022

COPYRIGHT© NOTICE

All images are the property of Telco. Telco does not permit any unauthorised use or reproduction without prior written consent. All rights reserved.