


Applications

Customer Group	Furniture – Gluing station
Country	Poland
Product	PA 11 + LT/LR 100
Variations	
Application   	
Details LT and LR sensors installed in a gluing station of furniture production. They cannot be cleaned and therefore they have to be replaced after a certain time due to the accumulation of glue on the sensor lenses. Surprisingly, they work for up to two years before having to be replaced.	
Reference: TELCO 180207 1087	

COPYRIGHT© NOTICE

All images are the property of Telco. Telco does not permit any unauthorised use or reproduction without prior written consent. All rights reserved.